

## NEW HEADQUARTERS BUILDING Construction Progress Report 18 February 1963

Main Building STATINTL

Building Access for	The "SERVICE" badges which
STATINTL previously allowed unesco	rted access were rescinded 1 February.
STATINTL Since then visits by	to investigate air conditioning
problems and follow-up punch list items	have been severly curtailed because
it is impractical to escort them around t	he building. The Office of Security will
expedite their clearance for no-escort a	ccess, but it will require a minimum
of 30 days. Their personal history state	ements are now being submitted.

C O P Y

TRANSMITTAL SLIP DATE	
TO: Colonel Echranda 1550	
ROOM NO.	BUILDING
REMARKS:	
The	I. White har
by Co	I. White has
ham	taken can of
	$\sigma$ .
FROM:	
ROOM NO.	BUILDING
FORM NO .241	REPLACES FORM 36-8 GPO:1957O-439445 (47) WHICH MAY BE USED.

STATINTL